

The importance of monitoring Hydrogen Sulfide from an enclosed space, and effects of H2S on personnel that come into contact with this toxic gas.

Hydrogen Sulfide is a naturally occurring chemical that can be produced by bacteria in low oxygen environments. H2S is a colorless, sweet-tasting, poisonous gas with a pungent rotten egg odor. Hydrogen Sulfide is often referred to as stinkdamp due to its pungent smell. It is utilized in many industries around the globe, despite its extremely hazardous nature. Due to the high levels of flammability and toxicity, work personnel must be aware of the many health risks and safety precautions they must take when working with or around hydrogen sulfide.

**Chemical Properties** 

<u> </u>	
CAS Number: 7783-06-4	
Molecular Weight	34.1 g/mol
Boiling Point	-77°F/60°C
Freezing Point	-122°F/-85.5°C
Melting Point	-121°F/-85.4°C
Relative Vapor Density (air=1)	1.19
Auto-ignition Temperature	518°F/270°C

H2S can be dissolved in both water or oil. When the liquid is heated, depressurized, or agitated fumes can be accidentally released in the air. Hydrogen sulfide gas is 19% heavier than air and travels more effortless along the ground; setteling into low areas with poor ventilation. This can create a toxic and dangerous situation if personnel were to enter areas where gas may be present.

Utilizing MineARC's air quality management products can closely monitor gas levels to ensure the safety of workers during an emergency.

## **Health Effects of Hydrogen Sulfide Exposure**

The health effects of H2S depend on four variables: time, concentration, frequency, and health of the individual. The side effects from low levels of hydrogen sulfide can irritate your eyes, nose, throat, and respiratory system. These effects can be delayed for several hours to even days after the onset of exposure. Moderate exposure can cause severe eye and respiratory irritation, headaches, dizziness, nausea, and vomiting. As exposure becomes more intensified, it will attack the nervous system. Higher levels of exposure can cause anoxia1, the absence of oxygen in the arterial blood and tissues, paralysis of the respiratory system, rapid unconsciousness, coma, and death.

### Effects of H<sub>2</sub>S

PPM	EFFECT TIME				
0.01-1.5	Odor threshold - rotten egg smell				
10	Permissible exposure level - 8 hour				
20-30	Possible fatigue, loss of appetite, headache, irritability, poor memory, dizziness. Intense odor.				
50-100	Mild irritation - eyes throat - 1 Hour				
100-150	Loss of smell (olfactory fatigue or paralysis)				
200-300	Significant irritation. Marked conjunctivitis & respiratory tract - 1 hour. Pulmonary edema may occur from prolonged exposure - 48 hours.				
500-700	Staggering, unconsciousness in 5 minutes. Serious eye damage, 30 minutes. Death 30-60 minutes				
700- 1000	Rapid unconsciousness, knockdown, or immediate collapse after 1-2 breaths. Breathing stops. Death in minutes.				
>1000	Nearly instant death				

The general industry ceiling limit for exposure limits in the United States are as follows:

- NIOSH (RELs) is 10 ppm (15mg/m<sup>3</sup>)
- OSHA (PELs) is 20 ppm to 50 ppm with 10-minute max peak.

Anoxia is a condition in which there is an absence of oxygen supply to an organ's tissues although there is adequate blood flow to the tissue,



The importance of monitoring Hydrogen Sulfide from an enclosed space, and effects of H2S on personnel that come into contact with this toxic gas.

# **Safety Hazards of H2S**

Hydrogen Sulfide is a highly flammable explosive gas that can cause life-ending situations if not properly handled. When burning H2S there's a high possibility of producing other toxic gases and vapors such as sulfur dioxide, another highly toxic gas. The explosive rate of hydrogen sulfide in the air is 4.5 to 45.5%. This range is much higher than the permissible exposure limit (PEL).

The liquid form of hydrogen sulfide can cause frostbite. If clothing becomes exposed to the liquid, it should be removed immediately and isolated, avoiding all sources of ignition. Clothing must be left until all liquid has evaporated.

OSHA requires strict precautions for workers at all times when working in confined spaces. Per OSHA's guidelines, ventilation should operate continuously. It is imperative to train your personnel on hazardous chemicals and gases, establish proper rescue procedures, and employers must provide proper respiratory protection equipment and other PPE such as eye protection and fire-resistant clothing to all personnel.

### **Acute Exposure Guideline Levels**

Acute Exposure Level Guidelines of chemical concentration set by the Environmental Protection Agency provides emergency responders with a clear reference tool when dealing with an accidental release of H2S.

	10 Mins	30 Mins	60 Min	4 HR	8 HR
AEGL 1	0.75ppm	0.60ppm	0.51 ppm	0.36 ppm	0.33 ppm
AEGL 2	41 ppm	32 ppm	27 ppm	20 ppm	17 ppm
AEGL 3	76 ppm	59 ppm	50ppm	37ppm	31ppm

AEGL 1 - Airborne concentration of a substance at which an individual could experience notable discomfort, irritation, or certain asymptomatic non-sensory effects.

AEGL 2 - Airborne concentration of a substance at which an individual could experience serious, long-lasting effects or an impaired ability to escape.

AEGL 3 – Airborne concentration of a substance at which the individual could experience life-threatening health effects or death.

# **Gas Detection Equipment for Enclosed Environment**

It is necessary to monitor the air quality when personnel are working in a space that contains hydrogen sulfide. Gas detection equipment can ensure the safety of personnel and compliance in confined spaces. H2S can be detected by its potent smell when concentrations are as low as 1 ppm.

MineARC has a variety of gas monitors, such as the Aura-PT Handheld Gas Detector and the Aura-FX Fixed Gas Monitor. The Aura-PT is a digital handheld gas detector that can continuously monitor H2S levels to ensure they remain within a safe range (below 10 ppm). The monitor utilizes an electrochemical gas sensor which measures the concentration of H2S by oxidizing at an electrode then measures the resulting current. The sensor has a range from 0-50 ppm.

The Aura-FX Digital Gas Monitor assists in maintaining a lifesupporting atmosphere within a refuge chamber. This device closely monitors and alerts occupants when levels change so they can take corrective measures to maintain a stable environment until they are rescued or it becomes safe to leave the chamber.

For further information, please visit www.minearc.com or email **info@minearc.com** to speak with a MineARC representative.

